



YES N/A
PLEASE DOUBLE CHECK WORDING
*Type had to be reset
 for cleaner imprint
 (original art was not vector)*


Header Card for SOC



SOC-Socket Outlet Covers



Dotted line shows Imprint area



THIS ORDER WILL NOT BE PROCESSED UNTIL THIS PROOF IS RETURNED
 Printing can take up to 5 days from time we receive signed art approval.

OE 0 SOC Prod. # SOC

Art Link	APP IN	Proof OUT	Proof IN	ART C	APP C	Film Print

ART APPROVAL FORM
 Fax Proofs are not true to size due to fax image shrinkage.

ATTENTION: This proof is for your protection against inadvertent errors. While every attempt is made to avoid errors or omissions in artwork, final proofing and approval must rest with the customer.
PLEASE REVIEW WITH CARE! Signature below releases printer from any liabilities of typographic or any other proof errors.
THIS ORDER WILL NOT BE PROCESSED UNTIL THIS PROOF IS RETURNED.
 Printing can take up to 5 days from time we receive signed art approval.

Please Check One : O.K. AS IS O.K. w/ CHANGES MAKE CHANGES AND FAX NEW PROOF
 Date: _____

Signature: _____ Print: _____

P.O. NO. _____ 0 _____
 IMPRINT COLORS _____ 0 _____

 PRODUCT COLOR White
 IMAGE PLACEMENT 2 -sides Header Cards

1 - side ISOCS